

---

SprintScan Driver Version 2.7x Readme File

(c) 1999 Polaroid Corporation

---

CONTENTS

=====

1. Current released versions of Legacy SprintScan Drivers
  2. The new PolaColor Insight software driver versus the legacy SprintScan 2.7x driver.
  3. New! Version 2.7.1 Macintosh G3/G4 compatibility
  4. Polaroid Customer Support Information
- 

1. Current released versions of Legacy SprintScan Drivers
- 

Version 2.7.1 for the Macintosh  
Version 2.7.2 for the PC

---

2. PolaColor Insight Versus 2.7x
- 

Polaroid released a new scanner driver with color/image correction software that is compatible with the SprintScan 35 and 35 Plus. Our older, legacy, color/image correction SprintScan software (version 2.7x), is still usable and we are continuing to offer it as a convenience to our customers. This SprintScan legacy software might provide better results (compared to PolaColor Insight) when scanning dark images or underexposed film.

---

3. New! Version 2.7.1 Macintosh G3/G4 compatibility
- 

Mac version 2.7.1 is an update to the last released version 2.7 for the Macintosh. The updated version will run on the blue and white G3 and G4 computers.

---

4. Polaroid Customer Support Information
- 

Before calling, refer to the "PolaColor Insight Software User's Guide" for assistance.

For product support information on the World Wide Web, access the Polaroid World Wide Web sites:

<http://www.polaroid.com> (U.S. and worldwide site)

<http://www.polaroid.de>  
<http://www.polaroid.co.uk>

Call toll-free from within the U.S.:  
1-800-432-5355  
Monday through Friday,  
8 a.m. to 8 p.m. (Eastern time)  
Or fax: 781-386-9688

In Canada, call:  
1-800-268-6970